

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

43521A-03

S E R V I C E N O T E

Supersedes:
[None]

Agilent 43521A Downconverter

Serial Numbers: See Solution / Action

Power Supply Switch Part Number Change

Parts Required: See Solution / Action

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: TO PRODUCT LINE: WN

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2003
PRINTED IN U.S.A.

January 29, 2003



Agilent Technologies

Situation:

The wire assembly (P/N 43521-61637) with power switch of the 43521A and the angle (P/N 43521-01209) for this assembly were obsoleted and replaced with new parts.

Solution/Action:

When replacing the wire assembly or the angle, order appropriate parts depending on the serial number of the 43521A.

Serial Number: JP1KG00301 and below

When replacing the wire assembly (P/N 43521-61637) or the angle (P/N 43521-01209), replace all the parts listed in Table 1 with the new parts shown in Table 2.

Serial Number: JP1KG00302 and above

When replacing the wire assembly or the angle, use the replacement parts listed in Table 2

Table 1 Old Parts

Part Number	Qty.	Description
43521-61637	1	Wire assembly with power switch
43521-01209	1	Angle
0510-0905	2	Screw to fix the wire assembly and angle
2190-0583	2	Spring washer

Table 2 New Replacement Parts

Part Number	Qty.	Description
43521-61649	1	Wire assembly with power switch
43521-01211	1	Angle
0510-0914	2	Screw to fix the wire assembly and angle

Note: Spring washer is unnecessary for 0510-0914