

S E R V I C E N O T E

SUPERSEDES: 4352B-06

4352B VCO/PLL Analyzer**Serial Numbers:** 4352B: JP1KE00196 / JP1KE00207**Don't use old GSP board to the 4352B equipped new LCD****To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

P/N	Description	Quantity
E4970-66554	GS P	1

Situation:

The 4352B specified above contains the new LCD (P/N 2090- 0574). The old GSP board (P/N E4970-66552) is designed for the old LCD (P/N 2090-0534) but not for the new LCD (P/N 2090-0574).

Solution / Action:

Use the new GSP board (P/N E4970-66554) when the originally installed GSP board become defective. Don't use the old GSP board (P/N E4970-66552) anymore.

DATE: July 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

HN

ENTITY:

3355

ADDITIONAL INFORMATION:

