

## S E R V I C E N O T E

SUPERSEDES: None

**HP 4934A Transmission Impairment Measuring Set**

Serial Numbers: 0000U00000/9999U99999

**Fuse in Neutral Line - not Live Line**

All the HP 4934A's which have been shipped, have the fuse in the Neutral line and NOT the Live line as shown in the schematic diagram in the Service Manuals.

This does not constitute a hazard and meets the published specifications of IEC348 and CSA BULLETIN 556B.

A manual change sheet for each of the Service Manuals will be issued, showing the fuse in the Neutral line.

The design will eventually be changed to have the fuse in the Live line and a Service Note to this effect will be issued at that time.

DATE: March 1997

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR:

GS

ENTITY:

1400

ADDITIONAL INFORMATION: