

S E R V I C E N O T E

SUPERSEDES

HP 4937A Transmission Impairment Measuring Set

Serial Numbers: 0000A00000 / 9999A99999

Suggested replacement volume control assembly for older instruments

Situation:

The vendor for the volume control pot, p/n 2100-3858, will no longer be manufacturing this part. A replacement for the 2100-3858 was found that has a different lead pattern which the 4937A can not accommodate. Since the 4937A is in its five year support life, a volume control assembly has been designed for use as a replacement for the 2100-3858.

Solution/Action:

A new volume control assembly has been designed for the replacement on the 04937-60001. Order p/n 04937-62901 when replacing the volume control pot, R20, on the 4937A's A1 assembly.

NOTE:

There is a very limited quantity of the old volume pot, p/n 2100-3858, available for supporting the 4937A.

DATE: 15 September 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: R.C.B.	ENTITY: 3800	ADDITIONAL INFORMATION:
-------------------------------------	-----------------------------------	---------------------------------------