

S E R V I C E N O T E

SUPERSEDES: NONE

4957A Protocol Analyzer**Serial Numbers:** 0000A00000 / 9999A99999**Redesigned CRT for the 4957A****Situation:**

The mounting ears on the old CRT, p/n 2090-0202 interfere with the floppy disc drive when assembling the top and bottom covers of the 4957A.

Solution/Action:

The CRT in the 4957A has changed from part number 2090-0202 to 2090-0294. When replacing a faulty CRT in the 4957A order the new CRT, p/n 2090-0294.

DATE: 15 SEPTEMBER 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

RCB

ENTITY:

3800

ADDITIONAL INFORMATION:

