

S E R V I C E N O T E

SUPERSEDES: NONE

4957A Protocol Analyzer**Serial Numbers:** 0000A00000 / 9999A99999

Fan

New Fan for the 4957A**Situation:**

The present fan assembly (P/N 04991-68501) was found to cause electrical interference with the CRT circuitry.

Solution/Action:

The new part number for the fan assembly is 04957-68501. Order this part number when replacing the fan assembly.

DATE: 22 OCTOBER 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

RCB

ENTITY:

3800

ADDITIONAL INFORMATION:

