

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

53147A-02

S E R V I C E N O T E

Supersedes:
NONE

53147A - 20 GHz Microwave Counter/Power Meter/DVM

Serial Numbers: 0000A00000/US99999999

The silk screen information on the rear panel of most units shipped before March 2002 says that the AC power mains fuse is a 1.5A T 250-volt fuse [2110-0304]. Later units have this information changed to 1.0A T 250V.

All units have been shipped with two 1-ampere fuses [2110-0007]. This is also the part number that is specified in the Assembly-Level Service Guide. It has been determined that if someone has installed 1.5-ampere slow blow fuses because of the rear panel information, that the product is still adequately protected from fault current. There is no compelling reason to change back to 1.0-ampere fuses. Either value provides adequate protection.

1111 ADMINISTRATIVE INFORMATION

| |
|---|
| SERVICE NOTE CLASSIFICATION: INFORMATION ONLY |
| AUTHOR: CJF PRODUCT LINE: 9E |
| ADDITIONAL INFORMATION: |

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.

February 27, 2002

