

S E R V I C E N O T E

SUPERSEDES: None

6035A Autoranging DC Switching Power Supply

Serial Number: See Below

Installing New Fan**Duplicate Service Notes:**

6010A-10	0000A00000/US37110121
6011A-11	0000A00000/US35460131
6012B-09	0000A00000/US35430201
6015A-06	0000A00000/US37050106
6030A-19	0000A00000/US37020171
6031A-21	0000A00000/US35430221
6032A-20	0000A00000/US35420521
6035A-09	0000A00000/US37020151

To Be Performed By: Agilent-Qualified Personnel**Situation:**

Old fan p/n 3160-0097 is being replaced by p/n 3160-0899.

Solution / Action:

When replacing the old fan with the new one, make sure the direction of air flow from the fan is going into the unit.

DATE: August 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

GS

ENTITY:

2100

ADDITIONAL INFORMATION: