

6264B-05

S E R V I C E N O T E

SUPERSEDES: None

HP 6264B DC Power Supply

Serial Number: 0000A00000 / 3018A08760

Main power transformer has been changed and is not directly interchangeable with previous transformers.

To Be Performed By: HP-Qualified Personnel

Parts Required: Transformer 06264-80091

Situation:

The new 06264-80091 transformer has a thermal fuse to protect against overheating during a fault by opening the bias transformer primary. The old shield (SH2) has been removed and the thermal fuse terminal (F2) is at the old location of the shield terminal. If the new transformer is wired the same as previous units it will blow the thermal fuse.

Solution:

In units using the previous transformer the thermal fuse is not used. After replacing the transformer remove the Green/ Yellow wire that formerly went from SH2 to chassis ground. Wiring to all other connections remains unchanged.

DATE: 19 November 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
DF	2100	

© 1992 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

