

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

6571A-05

S E R V I C E N O T E

Supersedes:
None

6571A DC Power Supply

Serial Numbers: 0000A-00000 / 3145A-00233

Chassis Replacement Requires New Keypad PCA

Parts Required:

P/N	Description	Qty.
5060-3396	Service Kit (Keypad PCA)	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: RJM PRODUCT LINE: 33
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



September 6, 2002

Situation:

The ESD post's location on the front chassis housing has been moved. The new ESD post location will interfere, and not fit correctly with the old front panel keypad board PCA.

When replacing the chassis on older instruments within the given serial number range, you must also replace the keypad board PCA.

Solution/Action:

A new Keypad board PCA must be used with the new chassis p/n 5060-3385 (Old Chassis p/n 5060-3334).

Use service kit p/n 5060-3396, which includes installation instructions, a tested keypad PCA, a cable, and screws.