# S E R V I C E N O T E

SUPERSEDES: None

# 66000A DC Power Supply System Mainframe

**Serial Numbers:** 3138A00122 / 3317A00505

## Unit resets when in serial link mode

To Be Performed By: Agilent-Qualified Personnel

Parts Required: PRGMD-ROM P/N 66000-80009

#### **Situation:**

When two 66000A mainframes are connected for serial link communication, commands to one mainframe may cause the second to reset to the turn on state.

## **Solution/Action:**

A new ROM revision eliminates this problem. Disassemble the mainframe to gain access to the main board. Replace the plug-in ROM, U51 revision A.00.02, with the new revision A.00.03.

Install a Power Supply Module and program the supply to insure the mainframe passes self test and accepts programming commands (either from the 66001A keyboard or via the GPIB).

DATE: 20 February 1993

# **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: Labor 1.0 Hour
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL:
AUTHOR: DF	ENTITY: 2100	ADDITIONAL INFORMATION:

© 1993 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

