6623A-16

SERVICE NOTE

Supersedes: NONE

6623A DC Power Supply

Serial Numbers: MY41000101 - MY41000216

Intermittent Power Transformer "Magmate" Connections

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

Model No.	Part Number	Description	Qty.
6621A	9100-4645	Power Transformer	1
6622A	9100-4490	Power Transformer	1
6623A	9100-4646	Power Transformer	1
6624A	9100-4561	Power Transformer	1
6625A	9100-4720	Power Transformer	1
6626A	9100-4591	Power Transformer	1
6627A	9100-4592	Power Transformer	1
6628A	9100-4720	Power Transformer	1
6629A	9100-4591	Power Transformer	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:							
MODIFICATION RECOMMENDED							
ACTION CATEGORY:	X IMMEDIATELY [[]] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS:	LABOR: 01 Hou	rs			
LOCATION CATEGORY: TEXT	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER	SERVICE INVENTORY:	X RETURN SCRAP [[]] SEE TEXT □ SEE TEXT	USED PARTS:	[[]] RETURN X SCRAP [[]] SEE SEE TEXT		
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RES	PONSIBLE UNTIL:	Support Li	fe of Product		
AUTHOR: RJM ADDITIONAL INFORM	PRODUCT LINE: 33 MATION:						

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



Page 2 of 2 6623A-16

Situation:

The power transformer vendor mistakenly installed the wrong "Magmates" in a run of power transformers. The incorrect "Magmates" have a # 43 stamped on them, which corresponds to a 15 gauge wire size. The correct size "Magmate" should be # 24 designed for a 19 gauge wire size.

This could result in a variety of intermittent as well as steady hardware problems and errors. Examples: HDW ERR CH 1, Blank front panel display, not meeting specifications.

Solution/Action:

Replace the Power Transformer with a new replacement Transformer, see the table above for the correct power transformer part number.

NOTE: Please inspect the new transformer for the correct "Magmate" number stamping.





