## 6634B-RECALL-10

# S E R V I C E N O T E

Supersedes: NONE

6634B Power Supply

Serial Numbers: US36380392

Calibrations performed on some Power Supplies by Agilent Technologies between July 1st, 2011 and July 31st, 2012 show a FALSE PASS in either one or more of the 4 tests: CC LOAD EFFECT, CV LOAD EFFECT, CC SOURCE EFFECT or CV SOURCE EFFECT.

Parts Required: P/N	Description	Qty.
NONE		

## **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	[[]] ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARDS  LABOR: 1.0 Hour			
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER [[]] CHANNEL PARTNER	SERVICE X RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT	USED PARTS:	[[]] RETURN [[]] SCRAP [[]] SEE TEXT	
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 31-July-2013			
X Calibration Required [[]] Calibration NOT Required		PRODUCT LINE: TJ AUTHOR: MW			
ADDITIONAL INFORMATION: Gratis Support need to be chosen as the billing type, while creating the customer order.					

© AGILENT TECHNOLOGIES, INC. 2012 PRINTED IN U.S.A.



Page 1 of 2

August 20, 2012

Rev. 20

Page 2 of 2 6634B-RECALL-10

### **Situation:**

The Quality issue is caused by a Test Software defect which caused a False Pass judgment. Agilent Service and Support corrected the Power Supply Test Software and installed it on all Test Systems by 31<sup>st</sup> July 2012,

#### **Solution/Action:**

- 1. Agilent will send a customer letter to all affected customers.
- 2. Customer, please contact nearest Agilent Customer Care Center and send instrument to Agilent for free calibration.
- 3. Agilent WCSS Service & Support to calibrate affected products at Agilent's expense.
- 4. After re-calibration Agilent to send the instrument back to the customer.