6655A-RECALL-11 <u>S E R V I C E N O T E</u>

Supersedes: NONE

6655A Power Supply

Serial Numbers: MY40000831, MY40000832

Calibrations performed on some Power Supplies by Agilent Technologies between July 1st, 2011 and July 31st, 2012 show a FALSE PASS in either one or more of the 4 tests: CC LOAD EFFECT, CV LOAD EFFECT, CC SOURCE EFFECT or CV SOURCE EFFECT.

Parts Required:P/NDescription

Qty.

NONE

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | | | |
|---|---|--|----------------|--|
| MODIFICATION RECOMMENDED | | | | |
| ACTION CATEGORY: | [[]] ON SPECIFIED FAILURE X AGREEABLE TIME | STANDARDS LABOR: 1.0 Hour | | |
| LOCATION CATEGORY: | [[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER [[]] CHANNEL PARTNER | SERVICE X RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT | USED PARTS: | [[]] RETURN [[]] SCRAP [[]] SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | NO CHARGE AVAILABLE UNTIL: 31-July-2013 | | |
| X Calibration Required [[]] Calibration NOT Required | | PRODUCT LINE: TJ AUTHOR: MW | | |
| ADDITIONAL INFORMATION: | | | | |

Gratis Support need to be chosen as the billing type, while creating the customer order.

© AGILENT TECHNOLOGIES, INC. 2012 PRINTED IN U.S.A.



August 20, 2012

Situation:

The Quality issue is caused by a Test Software defect which caused a False Pass judgment. Agilent Service and Support corrected the Power Supply Test Software and installed it on all Test Systems by 31st July 2012,

Solution/Action:

- 1. Agilent will send a customer letter to all affected customers.
- 2. Customer, please contact nearest Agilent Customer Care Center and send instrument to Agilent for free calibration.
- 3. Agilent WCSS Service & Support to calibrate affected products at Agilent's expense.
- 4. After re-calibration Agilent to send the instrument back to the customer.