

**6684A-05**

**S E R V I C E N O T E**

---

Supersedes:  
None

**6684A System Power Supply**

**Serial Numbers: 0000A00000 – MY41000109**

**“Replacement of the Bias or AC Input Boards ”**

**Situation:**

It has been decided to remove the “Dew Detector” feature, beginning with units with serial numbers greater than the given range. The bias and AC Input board part numbers have changed.

**Solution:**

The Bias board p/n that is compatible with older models with the Dew Detector is: 5065-6936.  
(Bias boards compatible with newer models without the dew detector feature use p/n: 5064-3450)

The AC Input board p/n that is compatible with older models with the Dew Detector is: 5065-6938.  
(AC Input boards compatible with newer models without the dew detector feature use p/n: 5064-0014)

**Parts Required:**

Bias Board: p/n 5065-6936  
AC Input Board: p/n 5065-6938

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: RJM      PRODUCT LINE: 33

ADDITIONAL INFORMATION: