S E R V I C E N O T E

SUPERSEDES: None

70100A MMS Power Meter

Serial Numbers: 0000U00000 / 9999U99999

Possibility of battery getting shorted when cover is replaced

Situation:

There is a possibility that replacing the covers on the 70100A MMS power meter can either short the battery or the battery circuitry. This has the effect or erasing the serial number and any power sensor data that has been entered.

Solution/Action:

Once the covers have been put on check that the serial number is still valid and re-enter it if necessary. To re-enter the serial number follow the procedure in the Troubleshooting section of the Service Manual. The serial number should be entered in the format 1234U56789.

DATE: January 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
	INFORMAT	TON ONLY
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
PN	E600	

© 1997 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

