

Supersedes:

None

HP MODEL 7045B X-Y RECORDER

Serial Prefix 2129A and Above

IMPROVED X AND Y AXIS ATTENUATOR ASSEMBLIES

The specifications of the rotary switch, P/N 3100-1666, have been changed to enhance the serviceability of the X and Y axis Range Attenuator Assemblies. The new assemblies are directly interchangeable with existing attenuator assemblies.

The attenuator assembly also uses a new vernier potentiometer, P/N 2100-3978. The old attenuator required the vernier potentiometer to have a non-standard bushing.

For component level replacement, note that the new vernier potentiometer (R12) cannot be installed on the older attenuator assembly; however, the old potentiometer can be installed on the new assembly.

I/NS/WN

8/81-11/DB



FOR MORE INFORMATION, CALL YOUR LOCAL HP SALES OR SERVICE OFFICE or East (201) 265-5000 • Midwest (312) 255-9800 • South (404) 955-1500 • West (213) 970-7500 or (415) 968-9200; **OR WRITE**, Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. **IN EUROPE, CALL YOUR LOCAL HP SALES or SERVICE OFFICE OR WRITE**, Hewlett-Packard S.A., 7, rue du Bois-du-Lan, P.O. Box, CH-1217 MEYRIN 2 - Geneva, Switzerland. **IN JAPAN**, Yokogawa-Hewlett-Packard Ltd., 9-1, Takakura-cho, Hachioji-shi, Tokyo, Japan 192.