

**81134A-02**

**S E R V I C E N O T E**

Supersedes:  
NONE

**81134A – High Speed Pulse Generator**

Serial Numbers: “ALL”

**81133/34A Firmware Version 2.95 Update available**

**Parts Required:**

P/N	Description	Qty.
NONE		

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:	
<b>MODIFICATION AVAILABLE</b>	
ACTION CATEGORY::	AGREEABLE TIME
	X PERFORMANCE ENHANCEMENT X SERVICE / RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE [ ] ON-SITE X SERVICE CENTER [ ] CHANNEL PARTNERS
	AVAILABILITY:12/01/2012
AUTHOR: FK	PRODUCT LINE: 24
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2011  
PRINTED IN U.S.A.

December 15, 2011

Rev. 18



**Agilent Technologies**

**Situation:**

Starting December 2011 channel modules with a new revision of hybrid amplifier chips are shipped which feature a new HW ID together with BIOS 1.20 and require a new FW version 2.95 to be supported.

**Solution/Action:**

The firmware package 2.95 is customer installable via GPIB, USB or LAN. An archive, including documentation with installation instructions can be downloaded from the Agilent homepage:

<http://www.agilent.com>