							8	115	0A-	03
S	Ε	R	V	C	Ε		N	0	Τ	Ε

Supersedes: NONE

Serial Numbers: ALL

Instrument refuses to boot if a front panel keyboard button is sticking.

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:								
INFORMATION ONLY								
AUTHOR: HK	PRODUCT LINE: PL24							
ADDITIONAL INFORMATION:								

© AGILENT TECHNOLOGIES, INC. 2008 PRINTED IN U.S.A.



October 6, 2008

Rev. 15

Page 2 of 2 81150A-03

Situation:

If a front panel key / button is sticking the you will see the following display:



The boot will stop and show the screen above.

You will get the same situation if

- a key was pressed accidentally during boot of the 81150A
- the keypad is defective and a "key is pressed all the time". In that case the front panel has to be replaced (see Service Guide for the 81150A)

Solution/Action:

Check all keys / buttons of the front panel. Identify the button that is sticking and make sure the button is in the right position. Then reboot the 81150A

If you have any questions contact:

bvs-pdga_support@agilent.com