S E R V I C E N O T E

SUPERSEDES: NONE

8146A Optical Time Domain Reflectometer

Serial Numbers: 0000A00000 / 9999Z99999

Recommended Flexible Disk Drive Replacement

To Be Performed By: Agilent-Qualified Personnel

Situation:

A production change at the manufacturer of the Flexible Disk Drive caused the drive to become unsuitable for replacement purposes.

By BID's process, the part is selected to guarantee full functionality in the 8146A.

When replacing the Flexible Disk Drive of the 8146A, the new selected part number 08146-67501 shall be ordered (instead of the original 0950-2122)

DATE: October 1995

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
VE	B100	

© 1995 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

