

S E R V I C E N O T E

SUPERSEDES: NONE

83236A PCS Adapter

Serial Numbers: 0000J00000 / 3617J00642

Replace the cover assy and the shield cover of CPU board.**To Be Performed By:** Agilent-qualified personnel**Parts Required:**

P/N	Qty.	Description
83215-60006	1	Cover Assy
83215-00668	1	Shield Cover

Situation:

Needs to replace the cover assy and the shield cover of CPU board A rivet of cover assy does cause damage to the shield cover.

Solution/Action:

Replace the cover assy and the shield cover of CPU board.

- a. Open the cabinet.
- b. Replace ths shield cover of CPU board (83215-66562).
- c. Replace the cover assy.

DATE: January 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ☒ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 0.25 Hours	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ SERVICE CENTER	SERVICE INVENTORY: ☐ RETURN ☒ SCRAP ☐ SEE TEXT	USED PARTS: ☐ RETURN ☒ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
AUTHOR: KM		AGILENT RESPONSIBLE UNTIL: January 1999	
ENTITY: 3355		ADDITIONAL INFORMATION: FQC-139619	