

S E R V I C E N O T E

SUPERSEDES: None

8481H High-power sensor, 10 MHz to 18 GHz**Serial Numbers:** 3318A20224 / 3318A20819

MY41090101 / MY41090105

MY41090107

MY41090108 / MY41090182

MY41090187

MY41090188 / MY41090192

ID Label (Maximum Power Limit) is incorrect**To Be Performed By:** Agilent-Qualified Personnel or Customer**Situation:**

The 08481-80003 8481H ID Label indicates a Maximum Power of 35 Watts.

Solution / Action:

This label should indicate a Max. Pwr. of 3.5 Watts. For all 8481H sensors returned for calibration or repair and cal, Agilent Service Centers are to replace all labels stating 35 Watts free of charge. Corrected labels will be available on ePal on or before 1 July, 2001.

In addition, cal and repair will be performed free of charge for customers who indicate that their sensor was damaged by applying RF power levels based on the incorrect 35W maximum.

DATE: June 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

TC

ENTITY:

BEST PGU
5390

ADDITIONAL INFORMATION:

