

S E R V I C E N O T E

SUPERSEDES: None

8487D Power Sensor

Serial Numbers: See Below

**MP10 thru MP22 English to Metric screw change.
(A2MP10 thru A2MP22 for 8481B / 8482B)**

Duplicate Service Notes:

- 8481A-06 Serial Numbers: 3318A99850 / 9999Z99999
- 8481B-01 Serial Numbers: 3318A10051 / 9999Z99999
- 8481H-02 Serial Numbers: 3318A18337 / 9999Z99999
- 8481D-01 Serial Numbers: 3643A15889 / 9999Z99999
- 8482A-02 Serial Numbers: 3318A29894 / 9999Z99999
- 8482B-01 Serial Numbers: 3318A06115 / 9999Z99999
- 8482H-02 Serial Numbers: 3318A07387 / 9999Z99999
- 8483A-04 Serial Numbers: 3318A07307 / 9999Z99999
- 8485A-02 Serial Numbers: 3318A16398 / 9999Z99999
- 8485D-01 Serial Numbers: 3318A03802 / 9999Z99999
- 8487A-01 Serial Numbers: 3318A02441 / 9999Z99999
- 8487D-01 Serial Numbers: 3318A01429 / 9999Z99999
- R8486A-01 Serial Numbers: 3318A03271 / 9999Z99999
- R8486D-01 Serial Numbers: 3318A00425 / 9999Z99999

Continued

DATE: October 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
EMC	5320	

To Be Performed By: Agilent-Qualified Personnel

Situation:

Screws with reference designations starting at MP10 thru MP22 have all changed from part number 3030-0954 (MP10-18) and part number 3030-0422 (MP19-22) to the metric part number 0515-0879.

Solution / Action:

In order to reduce the chance of stripped threads use only the metric screw (part number 0515-0879) as a replacement for MP10 thru MP22 on the above Power Sensors.