

S E R V I C E N O T E

SUPERSEDES: None

8514B S-parameter Test Set**Serial Numbers:** 0000A00000 / 9999Z99999 means all units.**New part number for VTO and frequency converter****To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

Part Description	Old Part Number	New Part Number
Frequency Converter	08514-60008	5087-7039
VTO	5086-7231	5087-7040
Rebuilt VTO	5086-6231	5087-6040

Situation:

Due to lower level component change, the frequency converter, VTO and rebuilt VTO part number have been changed.

The latest version of 8510 systems Performance Verification software Rev. A.05.00 should be used to verify the systems operation after repair.

Solution/Action: Order the new part numbers.

DATE: January 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ☒ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: Labor 2.5 Hours	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☒ ON-SITE ☐ SERVICE CENTER	SERVICE INVENTORY: ☐ RETURN ☐ SCRAP ☒ SEE TEXT	USED PARTS: ☐ RETURN ☐ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
AUTHOR:	ENTITY: 5340		
ADDITIONAL INFORMATION: Current service inventory can still be used.			

