

RF DEPT.
FILE COPY
DO NOT REMOVE

8515A-03

S E R V I C E N O T E

HP 8515A S-Parameter Test Set

Duplicate Service Notes:

8511A-02 8512A-05
8513A-03 8514A/B-01
8516A-06

Serial Numbers: 0000A0000/9999Z99999

Modification kit that contains all necessary components to add Option 001

Situation:

The Test Set Multiplexer Kit (H/P 08511-60008) contains all the components required to add Option 001 (formerly special option H01) to the standard 8511A-8515A series Test Sets. The kit consists of a multiplexer board, coaxial cable assemblies, labels, and documentation. Refer to the 8510-4 Product Note for operational information.

The 8515A does not have Option 001, but the Test Set Multiplexer kit will still provide IF switching capability to support multiple test set operation with the 8510B Network Analyzer.

Date: 08 May 1989

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	AGREEABLE TIME	☒ PERFORMANCE ENHANCEMENT ☐ SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☒ ON-SITE ☒ HP LOCATION	AVAILABLE UNTIL: End of Support Life
AUTHOR: JH	ENTITY: 4500	ADDITIONAL INFORMATION:

© 1989 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.



Parts Required:

HP P/N	Description	Quantity
08511-60008	Option 001 Upgrade Kit	
08513-60004	IF MULTIPLEXER BOARD	1
08513-60121	CABLE ASSEMBLY, A23J3-A2J7	1
08513-60122	CABLE ASSEMBLY, A13J3-A2J7	1
08513-60123	CABLE ASSEMBLY, A10J3-A2J4	1
08513-60124	CABLE ASSEMBLY, A11J3-A2J10	1
08513-60129	CABLE ASSEMBLY, A2J3-J10A1	1
08513-60130	CABLE ASSEMBLY, A2J9-J10A1	1
08513-60131	CABLE ASSEMBLY, A2J6-J10A2	1
08513-60132	CABLE ASSEMBLY, A2J12-J10A3	1
08513-60135	CABLE ASSEMBLY, A3J3-J10A7	1
08513-60137	CABLE ASSEMBLY, A3J6-J10A5	1
08513-60139	CABLE ASSEMBLY, A3J8-J10A6	1
9320-6027	CABLE LABEL, "A2J2"	1
9320-6027	CABLE LABEL, "A2J5"	1
9320-6027	CABLE LABEL, "A2J8"	1
9320-5959	CABLE LABEL "A2J11"	1
9320-5959	MYLAR LABEL "OPT 001"	1
08511-90027	INSTALLATION NOTE	1
5952-6674	8510-14 PRODUCT NOTE	1