

Supersedes:

NONE

**HP MODEL 8558B SPECTRUM ANALYZER**

Serials Prefixed 1321A and Below

**IMPROVED FREQUENCY TUNING POT**

The Frequency Tuning Pot may become noisy and erratic. This will be seen on the display as increased noise and jumpiness when tuning.

The recommended replacement Frequency Tuning Pot is HP 2100-0654. This pot should be used for all Tuning Pot replacements.

The Frequency Control Voltage Adjustment in the Operating and Service Manual should be performed after replacing the Frequency Tuning Pot.

JRB/KS/WO

1/74-45

**HEWLETT** **hp** **PACKARD**

For more information, call your local HP Sales Office or East (201) 265-5000 • Midwest (312) 677-0400 • South (404) 436-6181 • West (213) 877-1281. Or, write: Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. In Europe, Post Office Box 85, CH-1217 Meyrin 2, Geneva, Switzerland. In Japan, Yokogawa-Hewlett-Packard, 1-59-1, Yoyogi, Shibuya-Ku, Tokyo, 151.

Printed in U.S.A.