S E R V I C E N O T E

SUPERSEDES: None

8562E Option 042 Portable Spectrum Analyzer

Possible Shoulder Strap Failure Under Load



POSSIBLE PERSONAL INJURY

Serial Numbers: See Below

Duplicate Service Notes:

8560E-18-S 8560E/042 Serial Numbers: 3517A01927/3804A03382 8561E-14-S 8561E/042 Serial Numbers: 3517A01242/3804A02191 8562E-06-S 8562E/042 Serial Numbers: 0000A00000/3751A00632 8563E-18-S 8563E/042 Serial Numbers: 3517A04194/3804A08329 8564E-12-S 8564E/042 Serial Numbers: 3551A00394/3751A01087 8565E-12-S 8564E/042 Serial Numbers: 3551A00369/e751A00852

Continued

DATE: August 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
PRIORITY SAFETY		
ACTION CATEGORY:	IMMEDIATELY	STANDARDS: LABOR - See Text
LOCATION CATEGORY: See Text	☐ ON-SITE ☐ HP LOCATION	SERVICE RETURN USED RETURN INVENTORY: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	ALWAYS	HP RESPONSIBLE UNTIL: ALWAYS
AUTHOR:GPB	ENTITY:5320	ADDITIONAL INFORMATION:None

© 1998 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.



Page 2 Service Note:8562E-06-S

To Be Performed By: HP-Qualified Personnel, Customer

Parts Required:

HP P/N Description Quantity

1540-1130 Soft Carrying Case 1

Situation:

Hewlett Packard has learned that the stitching which fastens the shoulder strap to the bag on some soft carrying cases may fail the load test (four times the intended mass). Failure of the stitching can result in damage to the instrument and possibly personal injury.

Solution / Action:

The carrying case which came with option 042 instruments in the serial ranges called out should be sent back to HP for exchange. New cases will be supplied under warranty. This exchange also applies to 1540- 1130 Carrying Cases purchased separately from HP during the 1997 calendar year. Customers may arrange to have their cases exchanged by contacting the Microwave Instruments Division Spectrum Analyzer Support Line at (707)577-6801.