

S E R V I C E N O T E

SUPERSEDES: 8568B-11A

HP 8566B Spectrum Analyzers  
 HP 8567A Spectrum Analyzers  
 HP 8568B Spectrum Analyzers

Serial Numbers:

0000A00000/9999A99999

Duplicate Service Notes:

8566B-11B  
 8567A-01A  
 8568B-11B

**A15 CONTROLLER ASSEMBLY FIRMWARE REPLACEMENT KIT**

To Be Performed By: Customer or HP-Qualified Personnel

Parts Required:

Firmware Replacement Kit (See Table 1 for part numbers and contents.)  
 PAL HP part number 85660-80070 (See NOTE)

DATE: 13 November 1989

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		<b>MODIFICATION AVAILABLE</b>	
ACTION CATEGORY:	AGREEABLE TIME	<input checked="" type="checkbox"/> PERFORMANCE ENHANCEMENT	<input type="checkbox"/> SERVICEABILITY/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> HP LOCATION	AVAILABLE UNTIL: Support Life	
AUTHOR: BF	ENTITY: 5300	ADDITIONAL INFORMATION: Installation Note 5958-7130	

# 8568B-11B

## NOTE

The PAL is needed for firmware upgrade of HP 8568B Spectrum Analyzers with serial numbers 0000A00000/2445A00971 or HP 8568A Spectrum Analyzers that have been upgraded to an HP 8568B with the HP 8568AB Retrofit Kit (formerly HP 8568A + 01K) with serial numbers 0000A00000/2426A00316.

### Situation:

From time to time, firmware is changed to correct bugs or add enhancements.

### Solution/Action:

Firmware Replacement Kits are available to upgrade your spectrum analyzer. The Firmware Replacement Kits contain the latest version of firmware.

Kit Contents	HP8566B 085660-60270	HP 8567A 085670-60009	HP 8568B 085680-60197
Date Code	10.10.89	7.4.87	7.4.87
A15U37 EPROM	85660-80185	85670-80019	85680-80113
A15U38 EPROM	85660-80187	85670-80021	85680-80115
A15U39 EPROM	85660-80186	85670-80020	85680-80114
A15U40 EPROM	85660-80188	85670-80022	85680-80116