86100C-09

S E R V I C E N O T E

Supersedes: None

86100C Digital Communications Analyzer

Serial Numbers: MY47440517 and above

When replacing the power supply, 0950-3499, in an 86100C that has a Windows Vista License, you must add a label, 7121-8324, to the power supply.

Parts Required:

P/N Description Qty.

7121-8324 Windows Vista Downgrade label 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: bmh	PRODUCT LINE: 8F
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2008 PRINTED IN U.S.A.



October 1, 2008

Rev. 15

Page 2 of 2 86100C-09

Situation:

The power supply in the above DCA's includes a label explaining the Windows operating system downgrade from Windows Vista to Windows XP.

Solution/Action:

A new label must be added to the replacement power supply when the power supply is replaced.