

86100C-11

S E R V I C E N O T E

Supersedes:
NONE

86100C Digital Communications Analyzer Mainframe

Serial Numbers: MY00000000/MY47441184, SG00000000/SG47440122

New part number for 86100C chassis fan requires shorter mounting hardware.

Parts Required:

P/N	Description	Qty.
3160-4286	Fan, Tubaxial	1
0515-0374	Screw, M3/0.5 10mm Long	4

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: djs	PRODUCT LINE: 8F
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2009
PRINTED IN U.S.A.

January 21, 2010

Rev. 16



Agilent Technologies

Situation:

Chassis cooling fan PN 3160-0917 is obsolete and has been replaced by PN 3160-4286. The new fan requires shorter mounting screws, PN 0515-0374, Qty: 4

Solution/Action:

When replacing old style chassis fan 3160-0917 with new replacement part 3160-4286, use 0515-0374 M3x0.5 10mm long mounting screws or equivalent, as shown below. Quantity: 4

Parts ID:

Please inform customers they may require shorter mounting screws in addition to the fan when they are placing an order.

