

8648C-04

S E R V I C E N O T E

Supersedes:
NONE

8648C Signal Generator

Serial Numbers: 0000A00000-3618A99999 and 0000U00000-3442U99999

Reverser Power Protection (RPP) replacement kit for Option 1E6 and/or 1E2 requires additional cables to complete the repair

Parts Required:

P/N	Description	Qty.
08648-20129	Cable from FEB to Pulse Module	1
and		
08648-20130	Cable from pulse module to atten	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: PY	PRODUCT LINE: 15
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2008
PRINTED IN U.S.A.

June 17, 2008

Rev. 14



Agilent Technologies

Situation:

The current RPP replacement kit, 08648-60143 for 8648 RPP repair does not cater for unit with option 1E6 and 1E2. With option 1E6 and/or 1E2, it requires 2 additional cables which are the W9 08648-20126 and W10 08648-20130.

Solution/Action:

Whenever a unit with serial number below <3619A and <3443U, and having Option 1E6 and/or 1E2 comes in for RPP replacement, for you are require to order RPP replacement kit 08648-60143 and additional 2 cables which are the W9 08648-20126 and W10 08648-20130 to complete the RPP repair.