

**8648D-04**

**S E R V I C E N O T E**

Supersedes:  
NONE

**8648D Signal Generator**

Serial Numbers: 0000A00000-3618A99999 and 0000U00000-3442U99999

**Reverser Power Protection (RPP) replacement kit for Option 1E6 and/or 1E2 requires additional cables to complete the repair**

**Parts Required:**

| <b>P/N</b>  | <b>Description</b>               | <b>Qty.</b> |
|-------------|----------------------------------|-------------|
| 08648-20129 | Cable from FEB to Pulse Module   | 1           |
| and         |                                  |             |
| 08648-20130 | Cable from pulse module to atten | 1           |

**ADMINISTRATIVE INFORMATION**

|                              |                  |
|------------------------------|------------------|
| SERVICE NOTE CLASSIFICATION: |                  |
| <b>INFORMATION ONLY</b>      |                  |
| AUTHOR: PY                   | PRODUCT LINE: 15 |
| ADDITIONAL INFORMATION:      |                  |

© AGILENT TECHNOLOGIES, INC. 2008  
PRINTED IN U.S.A.

June 17, 2008

Rev. 14



**Agilent Technologies**

**Situation:**

The current RPP replacement kit, 08648-60143 for 8648 RPP repair does not cater for unit with option 1E6 and 1E2. With option 1E6 and/or 1E2, it requires 2 additional cables which are the W9 08648-20126 and W10 08648-20130.

**Solution/Action:**

Whenever a unit with serial number below <3619A and <3443U, and having Option 1E6 and/or 1E2 comes in for RPP replacement, for you are require to order RPP replacement kit 08648-60143 and additional 2 cables which are the W9 08648-20126 and W10 08648-20130 to complete the RPP repair.