

8971B-03A

S E R V I C E N O T E

SUPERSEDES: 8971B-03

HP 8971B Noise Figure Test Set

Serial Numbers: 0000A00101/9999A99999

New A2 Assembly

To Be Performed By: HP Service Center

Situation:

The preferred and recommended replacement for the A2 microprocessor assembly is 08971-60123. The 08971-60123 microprocessor assembly is shipped without the firmware installed.

Solution/Action:

When ordering the 08971-60123 microprocessor assembly for installation in the HP 8971B, also order EPROM part number 08971-80002. Install the 08971-80002 on 08971-60123 at A2U22.

DATE: 15 August 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: FS	ENTITY: 0400	ADDITIONAL INFORMATION:
-------------------	---------------------	-------------------------

© 1991 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

