E3300A IC-CAP Framework

Y2K update information. Product requires replacement software product 85199A revision 5.00 or above. E3300A designed to run on computer hardware and operating systems that will NOT be made Y2K compliant.

Situation:

Product obsoleted and replaced by 85199A. Product designed to operate on computer hardware and operating systems that will NOT be made Y2K compliant. Product could fail to operate after 1999 due to non-compliant computer hardware or operating systems. Product will NOT be migrated to Y2K compliant computer hardware or operating system. Customer must use replacement product.

Solution / Action:

Date: 26 Aug 1998

Install 85199A revision 5.00 or above replacement product. Customers NOT under current support contract must renew support agreement to receive replacement product at no-cost.

| * * | ****** | ****** | **** | * * * * * * * * * * * * * * | ***** |
|-----|------------------|---------------|------|-----------------------------|-------|
| * | | | | | |
| * | | INFORMATION | ONLY | | |
| * | | | | | |
| * | | | | | |
| * | AUTHOR/ENTITY: | Glenn Ingel / | 5342 | (HPED) | |
| * | ADDITIONAL INFO: | | | (/ | |
| * | | | | | |
| | | | | | |