

Information Only Service Note

Supersedes: NONE

E36106A DC Power Supply, 100V, 0.4A, 40W

Serial Numbers: ALL

The Problem – E36106A DC Power Supply will be replaced by E36106B DC Power Supply

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

[[]] Calibration Required × Calibration NOT Required PRODUCT LINE: SP AUTHOR: HS

ADDITIONAL INFORMATION:



© Keysight Technologies 2015-2019 Information Only Service Note Version 1.2 | October 8, 2019| Page 1 of 2

Situation:

E36106A DC Power Supply has been discontinued on March 1st, 2019. In conjunction with this discontinuance, E36106B has been identified as the replacement product.

The E36106B is a complete drop-in replacement product in form, fit and function, with improved ripple noise performance and added on rackmount capability. Please refer to the table below for the comparison between E36106A and E36106B DC Power Supply.

Feature		E36106A	E36106B
Color		Arctic White	Phantom Gray
Output Noise	Vrms	15mV	2.5mV
	Vpp	150mV	40mV
Rackmount Capability		No	Yes

If the E36106A inventory for exchange repair is depleted, we will replace the customer defective E36106A units with E36106B.

Solution/Action:

Please contact your nearest Keysight Technologies Customer Call Centre and send the E36106A DC Power Supply unit for repair.

Revision History:

Date	Service Note Revision	Author	Reason for Change	
08 Oct 2019	01	HS	As Published	