

# E3646A-05

## S E R V I C E N O T E

Supersedes:  
N/A

### E3646A DC Power Supply

Serial Numbers: MY53186001 to MY99999999

### New Error Message

**Parts Required:**

P/N	Description	Qty.
N/A		

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
<b>INFORMATION ONLY</b>	
<input type="checkbox"/> Calibration Required	PRODUCT LINE: WC
<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR: TL
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2013  
PRINTED IN U.S.A.

July 12, 2013

Rev. 21



**Agilent Technologies**

**Situation:**

There are some new error messages for E3646A power supply starting from serial number MY53186001 as shown in Table 1 below.

114	Header suffix out of range
120	Numeric data error
130	Suffix error
503	SPI data error
609	System ADC test failed

Table 1, new error messages list

**Solution/Action:**

Refer E3646A [User's and Service Guide](#) Chapter 4 Error Messages for more details.

**Revision History:**

Revision Number	Date	Author	Reason For Change
1.0		TL	As published