

E4093B-01

S E R V I C E N O T E

SUPERSEDES: None

HP E4093B PT300 Protocol Tester

Serial Numbers: See Text

Duplicate Service Notes:

E4095B-01
E3910B-01
E3939B-01
E4240B-01

Fan speed regulator no longer required

To Be Performed By: HP-Qualified Personnel

Parts Required:

5063-3501 Cooling Fan
Serials 02-0000/CA33170017 Assembly

Situation:

Cooling fans used in current production incorporate a temperature sensing speed control, which was previously discrete circuitry. When a new fan is used to replace an older fan, the discrete speed control circuitry is redundant and must be disabled.

Continued

DATE: 17 November 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

HS

Z600

© 1993 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.



Solution/Action:

- 1) Remove Fan Speed Control Module, part number 4010-0750, and discard.
- 2) Install new fan assembly, re-using grille from old assembly. Make sure that spacers provided with new fan assembly are used, to avoid breaking the fan housing.
- 3) Plug fan into the 3 pin connector labelled P507.