

E4208A/B-01

S E R V I C E N O T E

SUPERSEDES: None

**E4208 VXI SCSI Disk Module
Floptical Disk Drive / E4208-82958 /**

Serial Numbers: CA00000000 / CA99999999

Proper Care of the BSTS Floptical Drive

To be performed by: Customer or HP-Qualified Personnel

Parts Required: 5182-0984 Floptical Head Protector

Situation:

The floptical disk drive is a delicate assembly and may be susceptible to failure if proper precautionary procedures are not followed. Failure to adhere to these precautions voids the warranty.

Continued

DATE: January 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

HS

ENTITY:

Z600

ADDITIONAL INFORMATION:

© 1996 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.



Solution/Action:

Follow these steps to properly protect the floptical drive.

- 1) To properly protect the head of the floptical drive, insert a 5182-0984 floptical head protector in the drive when it is not in use, especially if the unit will be moved around. This includes, but is not limited to, movement of the system from bench to bench and/or removal of the SCSI disk module from the VXI mainframe.
- 2) Do not move the E4208 around when there is a floptical diskette in the drive. This can cause damage to both the drive and the diskette. A diskette is NOT a substitute for the Floptical Head Protector card p/n 5182-0984.
- 3) When shipping the drive, the drive module, or a system containing the module make certain that it is well protected from shock. Popcorn is not a good shock insulator, as the drive may shift around in the box. Ensure that the shipping container is well padded on all sides.