

## S E R V I C E N O T E

SUPERSEDES: NONE

**E4220A, Form-7 Transportable Mainframe  
Assembly: HIL-PS/2 Converter / E4220-60130****Serial Numbers:** CA33450000 / CA34190178**HIL-PS/2 Converter replacement may require additional cables.****To Be Performed By:** Agilent-Qualified Personnel**Parts Required:** E4200-64009**Situation:**

Early assemblies of the E4220A Form-7 Mainframe contain HIL-PS/2 converters with cables soldered in place. A change in suppliers resulted in the assembly being equipped with modular connectors, enabling the HIL cables to be plugged into the module.

**Solution/Action:**

Whenever a unit in the affected serial number range encounters a failure repairable by the replacement of the HIL-PS/2 converter, two HIL cables p/n E4200-64009 must also be ordered and installed.

DATE: January 1996

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

HS

Z600

