MODIFICATION AVAILABLE - PERFORMANCE EHMANCEMENT CHARGEABLE TO CUSTOMER SERVICE / RELIABILITY ENHANCEMENT CHARGEABLE TO CONTRACT IF THERE IS ONE.

E4438C-14A

S E R V I C E N O T E

Supersedes: E4438C-14

E4438C

Serial Numbers: [0000A00000 / 9999Z99999]

Customers with E4438C's with failing Frac-N assembly, E8251-60044 are eligible to have their product repaired at Agilent's expense until 1NOV2007.

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

| P/N | Description | Qty. |
|------------------|------------------|------|
| E8251-69044 | Frac-N assembly | 1 |
| OR: | | |
| E8251-60044 | Frac-N assembly | 1 |
| Optional, see So | olutions/Actions | |
| E4400-60253 | Hard disk Drive | 1 |

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | | |
|------------------------------|------------------------------------------------------------|---------------------------------------------------------------------|--|
| MODIFICATION AVAILABLE | | | |
| ACTION CATEGORY: | On specific failure | [[]] PERFORMANCE ENHANCEMENT X SERVICE / RELIABILITY ENHANCEMENT | |
| LOCATION CATEGORY: | [[]] CUSTOMER INSTALLABLE X ON-SITE X SERVICE CENTER | AVAILABLE UNTIL: 1NOV2007 | |
| AUTHOR: HLU ADDITIONAL INFO | PRODUCT LINE: 15 | | |

© AGILENT TECHNOLOGIES, INC. 2006 PRINTED IN U.S.A.



Page 2 of 2 E4438C-14A

Situation:

Customers with E4438C's with failing Frac-N assembly, E8251-60044, are eligible to have their product repaired and updated with a hard disk drive, if installed, as described in "Solution/Action" section of this Service Note at Agilent's expense until 1NOV2007.

Solution/Action:

Replace failed Frac-N assembly E8251-60044, and hard disk drive assembly E4400-60253 that has not been replaced since 1JAN2006 if required.