

E4990A-07

# Information Only Service Note

Supersedes:  
NONE

## E4990A Impedance Analyzer, 20 Hz to 10/20/30/50/120 MHz

Serial Numbers: ALL  
Manufacturing ID Number: N/A

Firmware Update to Fix E4990A-010 Adapter Setup Issue

Parts Required:  
NONE

---

### ADMINISTRATIVE INFORMATION

Calibration Required  
 Calibration NOT Required

PRODUCT LINE: WN  
AUTHOR: BS

---

ADDITIONAL INFORMATION:

---

**Situation:**

The E4990A unit with option 010 (20Hz to 10MHz) and firmware **A.02.13 and below** does not perform the adapter setup properly. There will be no effect on the measurement results if user does not perform adapter setup for their measurement.

**Solution/Action:**

Update E4990A's firmware to **A.02.20**.

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
23 Jan 2017	01	BS	As Published