E4991A-04

<u>SERVICE NOTE</u>

Supersedes: None

E4991A RF Impedance/Material Analyzer

Serial Numbers: MY43300401 or later

While replacing A20 Digital Mother Board, use the new part-numbers.

Parts Required: See Solution/Action

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: jm PRODUCT LINE: WN

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007 PRINTED IN U.S.A.



Agilent Technologies

April 24, 2007

Page 2 of 2 E4991A-04

Situation:


Part-numbers for A20 ATX Digital Mother Board and its screw have been changed.

Solution/Action:

Old P/N New P/N Description

0960-2372 E4991-62003 A20 ATX Digital Mother Board

0515-1250 0515-0430 Screw M3



- End of Document -