

E5070A-08B

# Information Only Service Note

Supersedes:  
E5070A-08A

## E5070A ENA Series Network Analyzer, 300 kHz to 3 Ghz

Serial Numbers: ALL

New Parts to perform attenuator upgrade have become unavailable. Refurbished parts are now available

### Parts Required:

P/N	Description	Qty.
5188-9406	Refurbished Step Attenuator, Exch	1
33321-60081	New Step Attenuator	1

### ADMINISTRATIVE INFORMATION

Calibration Required  
 Calibration NOT Required

PRODUCT LINE: WN  
AUTHOR: EB

ADDITIONAL INFORMATION:

**Situation:**

Parts to perform attenuator upgrade have become unavailable. Refurbished attenuators are now available to replace failed attenuators.

**Solution/Action:**

When the E5070A Internal Test fails at Step Attenuator Test Group, replace the old attenuator based on the part number of the currently installed attenuator as follows:

<u>Currently installed:</u>	<u>Replace with:</u>
33321-60059	5188-9406
33321-60069	33321-60081

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
10 Jul 2017	02	Eric Baker	As Published