

E5070B-12E

Information Only Service Note

Supersedes:
E5070B-12D

E5070B RF Network Analyzer, 300 kHz to 3 Ghz

Serial Numbers: ALL

New Parts to perform attenuator upgrade have become unavailable. Refurbished parts are now available

Parts Required:

P/N	Description	Qty.
5188-9406	Refurbished Step Attenuator programmable , Exch	1
33321-69068	Refurbished Attenuator Programmable 35dB 12GHz , Exch	1

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: WN
AUTHOR: EB

ADDITIONAL INFORMATION:

Situation:

Parts to perform attenuator upgrade have become unavailable. Refurbished attenuators are now available to replace failed attenuators.

Solution/Action:

When the E5070B Internal Test fails at Step Attenuator Test Group, replace the old attenuator based on the part number of the currently installed attenuator as follows:

<u>Currently installed:</u>	<u>Replace with:</u>
33321-60059	5188-9406
33321-60068	33321-69068

Revision History:

Date	Service Note Revision	Author	Reason for Change
10 Jul 2017	05	Eric Baker	As Published