

E5071A-08B

Information Only Service Note

Supersedes:
E5071A-08A

E5071A ENA Series Network Analyzer, 300 kHz to 8.5 Ghz

Serial Numbers: ALL

New Parts to perform attenuator upgrade have become unavailable. Refurbished parts are now available

Parts Required:

P/N	Description	Qty.
5188-9406	Refurbished Step Attenuator, Exch	1
33321-60081	New Step Attenuator	1

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: WN
AUTHOR: EB

ADDITIONAL INFORMATION:

Situation:

Parts to perform attenuator upgrade have become unavailable. Refurbished attenuators are now available to replace failed attenuators.

Solution/Action:

When the E5071A Internal Test fails at Step Attenuator Test Group, replace the old attenuator based on the part number of the currently installed attenuator as follows:

<u>Currently installed:</u>	<u>Replace with:</u>
33321-60059	5188-9406
33321-60069	33321-60081

Revision History:

Date	Service Note Revision	Author	Reason for Change
10 Jul 2017	02	Eric Baker	As Published