EE∩72Λ 11

Information Only Service Note

Supersedes: NONE

E5072A ENA Series Network Analyzer

Serial Numbers: ALL

Manufacturing ID Number: N/A

The Problem - Compatibility of New DSP Board with E5072A Firmware

Parts Required:

P/N Description Qty.

Refer Solution in Table 1.

ADMINISTRATIVE INFORMATION

[[]] Calibration Required

X Calibration NOT Required

PRODUCT LINE: WN AUTHOR: BS

ADDITIONAL INFORMATION: Compatibility of New DSP Board with E5072A Firmware



Situation:

There is design change of DSP board for E5072A from E5071-66671 to E5072-66671.

Solution/Action:

The new DSP board is compatible with later firmware version of E5072A but **not** with firmware version **B.02.20** and below. Please refer to Table 1 below for the compatibility.

Table 1 Compatibility of DSP Board with FW version of E5072A

E5072A	Old FW (B.02.20 and below)	New FW (B.02.30 and later)
E5071-66671 (Old DSP)	Work with the above FW revision	Work with the above FW revision
E5072-66671 (New DSP)	Does not Work with the above	Work with the above FW revision
	FW revision	

^{*} Ensure that the DSP Board replaced is compatible with the FW version

Revision History:

10 Aug 2016 01 BS As Published	Date	Service Note Revision	Author	Reason for Change
	10 Aug 2016	01	BS	As Published
	10 / 109 20 10	0 1		7.0 Fubition of