

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

E5091A-02

S E R V I C E N O T E

Supersedes:
NONE

Agilent E5091A Multiport Test Set

Serial Numbers: See Solution/Action

Power Supply Switch Part Number Change

Parts Required: See Solution

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: TO PRODUCT LINE: WN
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2003
PRINTED IN U.S.A.

August 27, 2003



Situation:

The wire assembly (P/N 04288-61632) with power switch of the E5091A was obsoleted and replaced with new parts. Chassis also changed to a new one in time with the assembly.

Solution/Action:

When replacing the wire assembly, order appropriate parts depending on the serial number of the E5091A.

Serial Number: JP1KJ00149 and below
MY42100107 and below

When replacing the wire assembly (P/N 04288-61632), replace it with all the new parts shown in Table 1.

Table 1 Replacement Parts

Part Number	Qty.	Description
E5091-61634	1	Wire assembly with power switch
04268-01203	1	Angle
0515-1946	2	Screw to fix angle to wire assembly

Serial Number: JP1KJ00150 and above
MY42100108 and above

When replacing the wire assembly or angle, use the replacement parts listed in Table 2

Table 2 Replacement Parts

Part Number	Qty.	Description
E5091-61634	1	Wire assembly with power switch
E5091-01204	1	Angle
0515-1946	2	Screw to fix angle to wire assembly
0515-1946	2	Screw to fix wire assembly to Chassis
E5091-00102	1	Chassis