

E8361C-03A

S E R V I C E N O T E

Supersedes:
E8361C-03

E8361C PNA Microwave Network Analyzers

Serial Numbers: US000000000/US999999999 (All)

E8361A and E8361C Automated Source Adjustment software needs to have greater functionality. Until this functionality is implemented on July 31, 2009, any source-chain component replacement and corresponding calibration process must be done in the Agilent factory.

Parts Required: None

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY	
AUTHOR: MF	PRODUCT LINE: WN
ADDITIONAL INFORMATION: Affected PNA models: E8361A and E8361C. Service Note History: E8361C-03 written Oct 24, 2008. E8361C-03A written March 13, 2009 - changed implementation date to July 31, 2009.	

© AGILENT TECHNOLOGIES, INC. 2009
PRINTED IN U.S.A.

March 16, 2009

Rev. 16



Situation:

E8361A and E8361C Automated Source Adjustment software needs to have greater functionality before it can be used by Service Center personnel or customers.

Solution/Action:

On July 31, 2009, a new version of the E8361A/C Automated Source Adjustment software will be released that will have greater functionality. In the meantime, any source-chain component replacement (see below) and the corresponding calibration process must be done in the Agilent factory.

Components in the Source Chain:

P/N	Description
E8361-60002 <i>-and-</i> E8361-69002	Source 20 Assembly
5087-7130 <i>-and-</i> 5087-6130	SOMA 50
5087-7249	SOMA 70