E8361C-06

S E R V I C E N O T E

Supersedes: NONE

E8361C PNA Microwave Network Analyzers

Serial Numbers: US00000000/US99999999 (ALL)

During System Verification test, E8361C analyzers that encounter errors while measuring the verification kit devices should upgrade to the most recent firmware and retry the test.

Parts Requi	ired:
-------------	-------

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR: MF	PRODUCT LINE: WN	
ADDITIONAL INFORMATION: Affected PNA models: E8361/2/3/4C and N5230C. Service Note history: E8361C-06 written August 31, 2009.		

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.



September 1, 2009

Rev. 16

Page 2 of 2 E8361C-06

Situation:

During System Verification test, some E8361C analyzers are experiencing errors while measuring the verification kit devices.

Solution/Action:

Download the most recent firmware and retry the test.