E8364C-03

S E R V I C E N O T E

Supersedes: NONE

E8364C PNA Microwave Network Analyzers

Serial Numbers: US00000000/US99999999 (ALL)

During System Verification test, E8364C analyzers that encounter errors while measuring the verification kit devices should upgrade to the most recent firmware and retry the test.

I al to itequileu.	Parts	Required	l:
--------------------	--------------	----------	----

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
INFORMATION ONLY			
AUTHOR: MF	PRODUCT LINE: WN		
ADDITIONAL INFORMATION: Affected PNA models: E8361/2/3/4C and N5230C. Service Note history: E8364C-03 written August 31, 2009.			

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.



September 1, 2009

Rev. 16

Page 2 of 2 E8364C-03

Situation:

During System Verification test, some E8364C analyzers are experiencing errors while measuring the verification kit devices.

Solution/Action:

Download the most recent firmware and retry the test.